



Sample Production Route Card



Client	order_no	print_date	part_number
Customer A	123-6754	09/13/2026	Part-001
revision	Material	Total Batch qty	Qty
A	SS-304		10
ISO9001			
IS-123564			



W0-Gear-006-Gear Assembly

#	Operation	Performed By	Qty	Date	Rejected	Notes	Certificate	Invoice
10	Material Order	John Smith	10	09/13/2026			1234	
20	CNC-1	Vlad Noland	10	09/13/2026				
30	Inspection	Lex Goldman	3	09/13/2026				
40	CNC-2	Vlad Noland	10	09/13/2026				
50	Inspection	Lex Goldman	3	09/13/2026				
60	Assembly	John Smith	10	09/13/2026			56378	

QA Inspector

Production Manager